



موانئ أبوظبي  
ABU DHABI PORTS

## NOTICES TO MARINERS

### FREE PORTS - AIDS TO NAVIGATION

**To: All Vessels, Shipping Agents, Marine Services Provider and all other concerned parties**

In order to enhance the safety of navigation within the Free Ports limits, the following changes for below Buoys and Beacons have been carried out:

#### **A- The New Free Port**

- a) A new shore Light Beacon to mark the southern breakwater of the entrance to the New Free Port has been installed. The details of the new installed breakwater Light Beacon are as follows (see attached picture as an example):

SN	Type	Color	Characteristics	Position	
				LAT	LONG
1	Shore Light Beacon	Yellow	FL.Y.5s	24° 31.990' N	054° 21.715' E

#### **B- The Free Port**

- a) Three Beacons have been removed (canceled) from the water. The details of the three removed water Beacons are as follows:

SN	Type	Color	Characteristics	Position	
				LAT	LONG
1	Port	Red	Fl(2)R.10s	24° 30.957' N	054° 21.623' E
2	Port	Red	Fl(2)R.10s	24° 30.867' N	054° 21.738' E
3	Starboard	Green	Fl(2)G.10s	24° 30.617' N	054° 21.994' E

- b) Two permanent breakwater Light Beacons have been installed. The details of the two new breakwater Light Beacons are as follows (see attached picture as an example):

SN	Type	Color	Characteristics	Position	
				LAT	LONG
1	Shore Light Beacon	Yellow	FL.Y.5s	24° 30.975' N	054° 21.595' E
2	Shore Light Beacon	Yellow	FL.Y.5s	24° 30.943' N	054° 21.659' E

## AD Ports Marine Notice

- c) The Light Characteristics of the following shore Light Beacon have been changed, other details remains as is:

SN	Type	Old Color	New Color	Old Characteristics	New Characteristics	Position	
						LAT	LONG
1	Shore Light Beacon	Red	Yellow	Oc.R.16s 7m	Fl.Y.5s 7m	24° 31.049' N	054° 21.613' E

- d) The Identifications Number of the following Green Lateral Buoys have been changed, other details remains as is:

SN	Old ID	New ID	Type	Color	Characteristics	Position	
						LAT	LONG
1	FP 9	FP 7	Starboard Lateral	Green	FL.G.3sec	24° 30.747' N	054° 21.516' E
2	FP 10	FP 9	Starboard Lateral	Green	FL.G.3sec	24° 30.637' N	054° 21.688' E

Mariners are required to navigate with caution.

**Note:** Affected Admiralty Chart: 3713 and 3715.



Example of the Shore Light breakwater Beacon

*for*

**Captain / Adil Banihammad**  
**Chief Harbour Master**  
**Abu Dhabi Ports**

